


MD1FJ Star-delta Time Relay Specification

6





- ① PW:green LED, power supply indication
 - ② R1: yellow LED, Relay 1 status indication
 - ③ R2:yellow LED, Relay 2 status indication
 - 4 Time range setting: 1s, 3s, 10s ... 500h
 - 5 Time value setting: 2% ... 100%
 - 6 Star-delta shift time: 20ms, 40ms ... 200ms

Products features:

■ Wide power supply range: 12-240V AC/DC

■ Wide time setting: 0.02s - 500h

■ Ten star-delta shift time: 20ms, 40ms ... 200ms

Technical data:

Rated voltage: 12 - 240 V AC/DC
Rated frequency: DC or 50/60Hz
Terminal type: Screw terminals

 Width:
 22.5 mm

 Height:
 92 mm

 Length:
 100 mm

 Time range:
 0.02s - 500h

Setting accuracy: $\pm 10\%$ Repeatability: $\pm 0.5\%$ Temperature drift: $\pm 0.05\%$ /°C

Voltage drift: $\pm 0.2\%/V$ Switching capacity: 10A/250 VAC

Electrical durability: 10^{5} cycles Mechanical durability: 10^{7} cycles IP degree: IP50/IP20 Temp. for operation: -40° C...60°C Temp. for storage: -40° C...85°C

Relay output: 2 c/o (SPDT)


Mounting: 35mm DIN rail

Standards: IEC61812-1、GB14048.5




Reference figure for MD1FJ:

T: 0.02s-500h A1-A2: 12-240V AC/DC, 50/60Hz — : 10A 250V AC/30V DC



Note: If A1-A2 is DC power supply, A1 must be positive, A2 must be negative

Fuction figure:



Delay time setting example

T delay for 10s

Turn the time range knob to 10s, turn the percentage knob to 100%,

Then the time setting value is: $T_{\lambda} = \text{Rang} * \text{Time} = 10s * 100\% = 10s$

Star-delta shift time for 60ms

Turn the knob Tt to 60ms, Then Tt = 60ms